



# PhilGEPS

Philippine Government Electronic Procurement System

Central Portal for  
Philippine Government  
Procurement Opportunities

## Bid Notice Abstract

### Request for Quotation (RFQ)

**Reference Number** 677902  
**Procuring Entity** OFFICE OF THE PRESIDENT  
**Title** 2500 Hrs Mandatory inspection of Bell Helicopter 412 Nr 1896  
**Area of Delivery** Metro Manila

<b>Solicitation Number:</b>	RIS # 08-08-1165	<b>Status</b>	<b>Pending</b>
<b>Trade Agreement:</b>	Implementing Rules and Regulations	<b>Associated Components</b>	1
<b>Procurement Mode:</b>	Direct Contracting	<b>Bid Supplements</b>	0
<b>Classification:</b>	Goods	<b>Document Request List</b>	0
<b>Category:</b>	Helicopters - Parts	<b>Date Published</b>	19/08/2008
<b>Approved Budget for the Contract:</b>	PHP 32,000,000.00	<b>Last Updated / Time</b>	15/08/2008 16:17 PM
<b>Delivery Period:</b>		<b>Closing Date / Time</b>	26/08/2008 17:00 PM
<b>Client Agency:</b>			
<b>Contact Person:</b>	Lucila Ortiz Sampana Presidential Staff Officer III Assets Management Office, Dona Filomena Bldg., San Rafael Street, Manila Metro Manila Philippines 1005 63-2-7342129 63-2-7361113 losampana_31@yahoo.com		

#### Description

2500 Hrs Mandatory inspection of Bell Helicopter 412 Nr 1896  
 Perform 2500-Hr Mandatory inspection/overhaul of the following:  
 1 ea Main Rotor Mast  
 1 ea Tail Rotor Hub Assembly PN 212-011-701-125  
 1 ea Main Transmisssion Assembly PN 412-706-029-103 (SN-A-257)  
 ea Swash plate and Support Assembly PN 412-010-402-11  
 1 ea Hub and sleeve Assembly PN 412-010-401-111  
 2 ea Hydraulic Cylinder Assemblies PN 212-076-005-105  
 1 ea Directional Hydraulic Servo Actuator PN 21-076-004-5  
 1 Fire Extigusher System PN 209-062-908-105 RH and PN 209-062-908-105 LH  
 1 ea Rephasing Lever Assembly PN 204-057-841  
 1 ea Cam to Upper Yoke (8) PN MS 1250H05-006  
 1 ea Lower Yoke to cam (8) PN MS 1250H05-006  
 1 ea Clevis to cam (4) PN AS66077D21  
 1 ea Clevis Assembly to Lower cam ( ) PN NAS 6608D48  
 1 ea MAin Drive Shaft Assembly PN 412-040-005-103

1 ea MAIn Rotor Hub Assembly  
 1 ea MAIn Rotor Blades  
 1 ea Tail Rotor Blades  
 1 ea Tail Rotor Drive Shafts  
 1 ea Tail Rotor Hanger Assemblies  
 1 ea Clutch Gear of Combining Gear Box  
 lot Re upholstery, replacement of carpet, repainting of aircraft  
 lot Calibration of Navigational equipment

Compliance of Service Bulletins / Technical Bulletin:

TB 41-04-197 - INTAKE SCREEN IMPROVEMENT  
 ASB 412-05-117 - TAIL ROTOR BLADES INSP. AND  
 ASB 412-00-106 - TAIL ROTOR BLADES ALL TIP BLOCK RETENTION MODIFICATION  
 ASB 412-00-105 - MAIN HYDRAULIC SERVO ACTUATOR ROD END LOCK WASHER, INSPECTION

FACILITY In Country Bell Certified  
 Warranty : 1 year  
 Delivery : 90 calendar days

Note: Direct Contracting with Hawker Pacific Asia PTE Ltd. per OP-BAC Resolution Nr. 23 dated 30 June 2008  
 The Draft Contract can be secured from the OP-BAC Secretariat.

**Created by** Lucila Ortiz Sampana  
**Date Created** 15/08/2008

The PhilGEPS team is not responsible for any typographical errors or misinformation presented in the system. PhilGEPS only displays information provided for by its clients, and any queries regarding the postings should be directed to the contact person/s of the concerned party.

© 2004-2008 DBM Procurement Service. All rights reserved.